

Action Plan for play area Wicksteed inspection report 23-11- 2017.

Wicksteed report comments	Risk level	Action required	Risk level on completion
Exposed liner material.	M	At base of slide, this is always an impact area. Rake bark surface and top up in summer with additional bark.	
Grass matting creates trip hazard, replace. Exposed mat pegs.	M	Cut out exposed and worn matting/pegs below swings and replace.	
Picnic table top decayed.	M	Repair top or replace bench.	
Timber fence broken fence rail.	MH	Repair rail or replace fence.	
Timber fence post broken off.	M	One post left of gate is not a post but a central support (not in the ground)? Post at play panel to replace.	
Pedestrian gate, spring is ineffective, access problem.	M	Remove spring and fit rope hoop to close gate as before. Dog fouling has never been a problem, only issue is with cats.	
Operators sign, generally satisfactory but recommendations for new pictorial sign.	M	Replace with new sign.	

Action plan prepared by Tim Kirby NVCA for consideration and action by Norton Parish Council, the operator.

Some Low risks have been noted in the report but are all managed or have been addressed in previous reports.

When completed this will reduce 6 medium and 1 medium/high risks to low with continued monitoring required. All other items inspected were assessed as low or very low.